



Spareparts



A		1
B		1
C		1
D		1
E		6
F		1

(Plan 1)



- 10-4365HVH-21-40 Connector Weldon (part "E" plastic)
- 10-4365-40 Connector Weldon (part "F" metal)
- 10-4365-50-10 Foot Weldon back white
- 10-4365-50-11 Foot Weldon front white
- 12-4361-42 Back cushion Weldon universal
- 12-4361-41 Seat cushion Weldon universal
- 12-4365-43 Back cush Weldon corner short
- 12-4365-42 Back cush Weldon corner long
- 315-77 Cover Weldon corner 1+2 grey
- 311-77 Cover Weldon universal 1+1 grey

Weldon
4365HVH-50-77
4361-50-77
4144-50-77
4367-50-77